

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

HAER No. UT-85-N

HAER
UTAH
6-LAY. V,
2N-

Hill Field, Equipment Repair Building
(Hill Field, Building 214)
(Hill Field, Building 106)
(Hill Field, Maintenance Building)
5909 Southgate Avenue
Layton vicinity
Davis County
Utah

Richard Dockendorf, Photographer. July 16, 1995

- UT-85-N-1 NORTH AND WEST FACING SIDES - LOOKING SOUTH.
- UT-85-N-2 WEST FACING ENTRANCE.
- UT-85-N-3 SOUTH FACING SIDE LOOKING NORTH.
- UT-85-N-4 EAST FACING END LOOKING WEST.
- UT-85-N-5 EAST AND NORTH FACING SIDES.
- UT-85-N-6 INTERIOR DETAIL SHOWING ORIGINAL CONSTRUCTION.
- UT-85-N-7 Photographic copy of construction drawing
6912-430 (from record group of Civil
Engineering, Hill Air Force Base, Utah).
Sept. 19, 1940. 8x10 negative and print.
HILL FIELD UTAH, EQUIPMENT REPAIR BUILDING
FIRST FLOOR PLAN.
- UT-85-N-8 Photographic copy of construction drawing
6912-431 (from record group of Civil
Engineering, Hill Air Force Base, Utah).
Sept. 19, 1940. 8x10 negative and print.
HILL FIELD UTAH EQUIPMENT REPAIR BUILDING
SECOND FLOOR PLAN AND DETAILS OF TOILET ROOMS.